
AIR SEPARATOR STRAINER AIR SEPARATOR AND STRAINER **ATAB**YLER "The New Form Of Energy"

Air And Dirt Separators

Air Separators



In water plant, air and water that are as solution become to gas according to the increase of temperature and start to circulate with the water in system. This air causes also to corrosion on boiler, combi boiler, pipe and armature in the plant. It also causes to noise and some heating problems in radiators. Our air separators prevent all of these



DN	50	65	80	100	125	180	200	260	30ti
EM	60,3	76.1	86,0	114,3	139.7	168,3	210.1	273	322,9
ž.	500	500	580	580	700	760	970	1210	1430
15	135	145	166	180	230	245	276	336	385
A .	169	109	219	219	324	324	406	500	600
nch.	30	11	20	187	17	30	4"	4-	40
0	209	260	369	360	324	574	650	750	850
DK DK	209	360	460	459	634	634	781	870	1006
Flow (f. mis mith)		15	20	30	80	75	125	200	275
Name of Street	1017	15716	91700	2075	SERE	48067	1000,000	940646	27022

Dirt Separators



Dirts and sediments cause to stuff on air filters when they aren't cleaned and they also block the water traffic. They also cause to some problems in circulation and some heating problems. Our dirt separators prevent this situation.



Welded/Flange	Technica	d Detail	s Of Co	nnectio	n.				
DN	50	65	80	100	120	150	200	290	300
EM	60,3	76.1	88,9	114.3	139.7	166,3	210.1	273	333,9
Į.	460	460	540	540	720	720	930	1170	1290
T	345	336	306	380	590	495	675	556	1025
A	100	169	210	219	324	304	406	500	600
Inch	10	1"	11	14	17	1"	90	2	-2"
st .	260	289	369	269	524	524	606	760	650
KS.	350	300	469	409	634	634	781	810	1000
Pipe (1 mis milh)	8	16	20	30	5/3	75	125	200	275
Weight Jugs	14/19	1602	2400	26/31	54/66	1666	120/122	222:246	380/425

ATADEMIR TUR. INS. MAK. SAN. TIC. LTD. \$11.

Modern Kerustiscker Stessi 4. Cd. 16.5K. No.3-5-5 Saray-Aszar-AnANATA TURKEY Pronce (LS12) 815 13.97 Fax: 0.(312) 815 13.98 was atatoyet com-independence (LS12) 815 13.97 Fax: 0.(312) 815 13.98